

Under Review Notification

Raised By: A. Kindeel

Product #: D3704

Date: 16.06.13

Product Name: ESCUTCHEON

| Part Number (D-Part and 9-Digit) | Drawing/Document & Current Affected Revision | "Y" or "N" Required for Each Part | | | | | | | Reserved ECN Log Number | Instructions Relevant to Each Part |
|-------------------------------------|---|-----------------------------------|--------------------------|------------------|-----------------|---------------|------------------|-------------------------------------|-------------------------|------------------------------------|
| | | HOLD SHIPMENT | Red Tag/Quarantine Stock | Advise Customers | Stop Production | Re-Work Stock | IPP Under Review | Product Specifications Under Review | | |
| D3704-3 | D3704 | Y | Y | N | Y | N | Y | Y | 16-597 | Revision to key hole cutout |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Description of Issue:
 Issues with current key hole depth resulting in lock being stuck in locked position.

Distribution:

| | | |
|----------------------------|------------------------------|----------------------|
| VP Operations | Chief Engineer | Production Engineers |
| Director of Operations | Engineering Project Managers | Planning Manager |
| Director Quality Assurance | Engineering Clerk | Program Manager |
| Director of Engineering | Customer Support Manager | |